

# Accessibility Report

## Transition Plan

Prepared By

**Disability Access Consultants, LLC**

(800) 743-7067

Prepared Using

**Facility Name :** 3 Lincoln St. -

**Date of Inspection :** 8/16/2021

Record Number : 16623  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16622  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15973  
Category : Reach Ranges  
Location : Exterior  
Description : Bus Stop  
Finding : The clear floor space length is not compliant.  
Recommendation : Provide compliant clear floor space.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$500.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Alfred Street & Franklin Street - Eastbound - Alfred Street &

**Date of Inspection :** 8/11/2021

Record Number : 15974  
Category : Reach Ranges  
Location : Exterior  
Description : Bus Stop  
Finding : The clear floor space slope is not compliant.  
Recommendation : Provide compliant clear floor space.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$500.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15975  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Sidewalk next to pad is not compliant.  
Recommendation : Provide a compliant sidewalk next to pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$25.84 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15976  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no clear floor space located next to bench.  
Recommendation : Provide compliant clear floor space next to the bench.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Alfred Street & Roberts Street - Westbound - Alfred Street &

**Date of Inspection :** 8/13/2021

Record Number : 16494  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16492  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : One  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16493  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Alfred Street & Union Street - Alfred Street & Union Street

**Date of Inspection :** 8/10/2021

Record Number : 15766  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15767  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 20238  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Commercial Street - 631 Elm Street

**Date of Inspection :** 8/24/2021

Record Number : 20239  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 20233  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 20234  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Community Center -

**Date of Inspection :** 8/10/2021

Record Number : 15972  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15971  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 19136  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Curran/Sterling -

**Date of Inspection :** 9/15/2021

Record Number : 25876  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25877  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 21010  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---



**Facility Name :** Drapeau/Morin -

**Date of Inspection :** 9/15/2021

Record Number : 21011  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25875  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25874  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : One  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Elm Street & Beacon Street - Northbound - Elm Street & Beacon

**Date of Inspection :** 8/20/2021

Record Number : 18942  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 18941  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 18940  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Elm Street & Union Street - Northbound - Elm Street & Union

**Date of Inspection :** 8/20/2021

Record Number : 18936  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 18937  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25831  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Fiber Materials -

**Date of Inspection :** 9/15/2021

Record Number : 25872  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25873  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25885  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Gooch/Elm -

**Date of Inspection :** 8/18/2021

Record Number : 25886  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 17375  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 17376  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The slope of the boarding pad/landing area is not the same as the street.  
Recommendation : Provide a compliant slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Hannaford -

**Date of Inspection :** 8/20/2021

Record Number : 17377  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 18938  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 18939  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Landry - 2 Landry Street

**Date of Inspection :** 8/24/2021

Record Number : 20236  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 20235  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 23335  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Main/Laconia -

**Date of Inspection :** 9/15/2021

Record Number : 23336  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25881  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25862  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Bus stop pad is not compliant.  
Recommendation : Provide a compliant bus stop pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$3,168.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---



**Facility Name :** Maine Behavioral Health -

**Date of Inspection :** 9/15/2021

Record Number : 25863  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Bus stop pad is not compliant.  
Recommendation : Provide a compliant bus stop pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$3,168.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25864  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Sidewalk next to pad is not compliant.  
Recommendation : Provide a compliant sidewalk next to pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$25.84      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25865  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Clear floor space within the bus stop shelter is not compliant.  
Recommendation : Provide compliant clear floor space in the shelter.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Marden's -

**Date of Inspection :** 8/21/2021

Record Number : 19134  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 19135  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The width of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25832  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Mountain Road -

**Date of Inspection :** 9/15/2021

Record Number : 25833  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Two  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25871  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25870  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Park & Ride -

**Date of Inspection :** 9/15/2021

Record Number : 25882  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25867  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no bus stop pad at the location.  
Recommendation : Provide a compliant bus stop pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$3,168.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25869  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no clear floor space located next to bench.  
Recommendation : Provide compliant clear floor space next to the bench.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Pate Plaza -

**Date of Inspection :** 9/15/2021

Record Number : 25868  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Bus stop shelter is not on an accessible route.  
Recommendation : Shelter shall be on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : One  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25878  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 19589  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Pool St/Foss St -

**Date of Inspection :** 9/15/2021

Record Number : 25884  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25883  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 15865  
Category : Pole Stops  
Location : Exterior  
Description : Alfred Street & Summer Street - Westbound  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Sokokis Rd -

**Date of Inspection :** 9/15/2021

Record Number : 25859  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no bus stop pad at the location.  
Recommendation : Provide a compliant bus stop pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$3,168.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25861  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no clear floor space located next to bench.  
Recommendation : Provide compliant clear floor space next to the bench.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25860  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Clear floor space is not located entirely within the shelter.  
Recommendation : Clear floor space shall be located entirely within the shelter.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Union/Orchard - Intersection Elm/Union/Orchard

**Date of Inspection :** 8/26/2021

Record Number : 20237  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 21009  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 21008  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---



**Facility Name :** Walgreens Crosswalks -

**Date of Inspection :** 8/12/2021

Record Number : 16282  
Category : Pole Stops  
Location : Exterior  
Description : Alfred Street & Dental Avenue  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16281  
Category : Pole Stops  
Location : Exterior  
Description : Alfred Street & Dental Avenue  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16621  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : No bus boarding pad/landing area is provided.  
Recommendation : Provide a compliant bus boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** Wentworth -

**Date of Inspection :** 9/15/2021

Record Number : 16620  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The information post is not located on an accessible route.  
Recommendation : Make sure the information post is on an accessible route.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : One  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25879  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25880  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The cross slope of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant cross slope.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

**Facility Name :** West Myrtle -

**Date of Inspection :** 8/12/2021

Record Number : 16303  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Sidewalk next to pad is not compliant.  
Recommendation : Provide a compliant sidewalk next to pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$25.84 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16302  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : Bus stop pad is not compliant.  
Recommendation : Provide a compliant bus stop pad.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Three  
Estimated Cost : \$3,168.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 16280  
Category : Bus Stops  
Location : Exterior  
Description : Bus Stop  
Finding : There is no clear floor space located next to bench.  
Recommendation : Provide compliant clear floor space next to the bench.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022 Completed Date : Priority : Two  
Estimated Cost : \$0.00 Actual Cost : \$0.00  
Contractor: Designated Staff: ADA Coordinator  
Comments : No Comments

---

Record Number : 25866  
Category : Pole Stops  
Location : Exterior  
Description : Pole Stop  
Finding : The length of the boarding pad/landing area is not compliant.  
Recommendation : Provide a compliant boarding pad/landing area.  
Progress : Not\_Set  
Resolution : Not\_Set  
Projected Date : 12/31/2022      Completed Date :      Priority : Three  
Estimated Cost : \$0.00      Actual Cost : \$0.00  
Contractor:      Designated Staff: ADA Coordinator  
Comments : No Comments

---

## Facilities Included in this Report

3 D's - 9/15/2021  
3 Lincoln St. - 8/16/2021  
39 Alfred Street (next to Police Dept) -  
8/10/2021  
Alex Pizza - 8/11/2021  
Alfred Street & Franklin Street - Eastbound  
- 8/11/2021  
Alfred Street & May Street - Westbound -  
8/13/2021  
Alfred Street & Roberts Street -  
Westbound - 8/13/2021  
Alfred Street & Union Street - 8/10/2021  
Beacon - 8/25/2021  
Commercial Street - 8/24/2021  
Community Center - 8/10/2021  
Courthouse - 8/21/2021  
Curran/Sterling - 9/15/2021  
Cutts - 8/26/2021  
Drapeau/Morin - 9/15/2021  
Elm Street & Alfred Street - Northbound -  
8/20/2021  
Elm Street & Beacon Street - Northbound  
- 8/20/2021  
Elm Street & Mason Street - Northbound -  
8/20/2021  
Elm Street & Union Street - Northbound -  
8/20/2021  
Emmons/Graham - 9/14/2021

Fiber Materials - 9/15/2021  
George Street - 9/15/2021  
Gooch/Elm - 8/18/2021  
Hannaford - 8/20/2021  
Happy Dragon - 9/2/2021  
Landry - 8/24/2021  
Library - 9/15/2021  
Main/Emery - 9/2/2021  
Main/Laconia - 9/15/2021  
Maine Behavioral Health - 9/15/2021  
Marden's - 8/21/2021  
Mason Street - 9/14/2021  
Mountain Road - 9/15/2021  
North Dam Mill - 9/15/2021  
Park & Ride - 9/15/2021  
Pate Plaza - 9/15/2021  
Pete's Auto - 8/23/2021  
Pool St/Foss St - 9/15/2021  
Post Office - 8/10/2021  
Sokokis Rd - 9/15/2021  
Tj's Pizza - 8/25/2021  
Union/Orchard - 8/26/2021  
Walgreens Crosswalks - 8/12/2021  
Water St/Mechanics Park - 9/2/2021  
Wellspring - 8/16/2021  
Wentworth - 9/15/2021  
West Myrtle - 8/12/2021  
YMCA - 9/15/2021

Prepared By  
**Disability Access Consultants, LLC**  
(800) 743-7067

Prepared Using